20 14%

25X1 25X1

Chief, Space, Maintenance & Facilities Branch, Office of Logistics

Deputy Director of Security (PPS), Office of Security

Security Construction - Curic Ball

113

REF.: Hemorandum dated 16 October 1957 from C/MRD to C/PhySD, subject: Security Specifications - Wings A, B, and C - Curie Hall

	1. The security storage problems releited to in the attached
	Bestorandus have been surveyed by Survey Branch,
	Physical Security Division, OS; in the company of
	Chief Machine Beauth Divided at 10 100
	Chief, Machine Records Division, Office of the Comptroller; and
25X1	of your office.
	2. The specific security construction items, noted on the
	attached floor plane by Mr. have been reviewed by
	OTS Cadadas (1995) and Other Lawrence by
	CIA Safety Officer, OS. He has advised that
	the CEA Fire Marshal disapproves of the proposal that a door be
	installed in the fire wall between the 1200 Wing of Curic Hall
	and Room 121. He also requests that an emergency exit door
	the state was been seen and been seen to be seen well as the seen seen seen seen seen seen seen se
	equipped with ber and bracket locking mechanism be installed in
	the left outside wall of the 1200 Wing, immediately to the front
	of the secure area. (Notations on attached floor plan)
	3 To maddalate and a street of a second
	3. In addition to the items noted on the attached floor plans
	end those suggested by it is requested that the following
	security construction items also be included.

Secure to door with carriage bolts; peen bolt ends.

b. Install empanded metal window grilles on windows in Rooms 1102, 1104, and 1106.

a. Install expanded metal on entrance door to 1000 Wing.

- c. Install expended metal on door leading from corridor into Room 123; secure metal to door with carriage bolts and peen bolt ends.
- d. In view of the nature of the material contained in these Wings, it is recommended that a rate-of-rise fire detection system be installed. It is noted that in order to

CHART

Approved For Release 2006/04/13 : CIA-RDP70-00211R000900110002-7

SUBJECT: Security Construction - Curic Hall

1 - 4/11/35/08; w/o attach <-

1 - SafO/OS, w/o attach 1 - SB Chrono, w/attach 1 - Reading, w/o attach

attain fire protection for the Wings involved in this request, it is necessary to install the rate-of-rise system in the entire west portion of the building. 25X1 4. It is requested that the Survey Branch, extension be notified upon completion of the above construction. Final survey and arrangements for the installation of MP type combination looks with escape mechanisms on the entrance doors of the respective areas will be made at that time. 25X1 Attachments: Ref. memo, w/floor plans Memo dtd 20 Dec 57 from CIA Safety Officer OS:PhySD/SB/ (27 Dec 57) Distribution: O&l - Addressee, w/attach 1 - OS/DD/FPS, w/o attach **ILLEGIB** 

**ILLEGIB** 

## Approved For Release 2006/04/13 : CIA-RDP70-00211R000900110002-7

UNCLASSIFIED CONFIDENTIAL SECRET  CENTRAL INTELLIGENCE AGENCY  OFFICIAL ROUTING SLIP  TO NAME AND ADDRESS INITIALS DATE	
OFFICIAL ROUTING SLIP	- 1
TO NAME AND ADDRESS INITIALS DATE	
	$\dashv$
1	
2	$\dashv$
3	╛
4	
5	
6	
ACTION DIRECT REPLY PREPARE REPLY	
APPROVAL DISPATCH RECOMMENDATION	$\dashv$
COMMENT FILE RETURN	_
CONCURRENCE INFORMATION SIGNATURE	
Hellyun see that air fele lepy neflects reply lower memo of MILISM through by security Cipy of memo of /nfs to Chief, Space, Maintenance Than March - H) -	s let
FOLD HERE TO RETURN TO SENDER	
FROM: NAME, ADDRESS AND PHONE NO. DATE	
Dived FainRelesse 2006/04/13 : CDAIRDF 90-00211R00096681	1/1

FORM NO. 237

Replaces Form 30-4 . which may be used.